

## LATEST DRY BULKER AUDIT SERVICE IN CHINA PORT



Carried out Opening meeting



Audit job in progressing











Forward view



After view



	
<p>Mid ship with draft markings</p>	<p>Accommodation ladder access</p>
	
<p>Save all with plug</p>	<p>Chains for securing of plugs not in position.</p>
	
<p>Fire hose in engine room (15m in length)</p>	<p>Life saving apparatus in engine room</p>
	
<p>Inventory of spare parts in storage</p>	<p>Inventory of spare parts for critical equipment</p>



Insulation resistance of 220V



Insulation resistance of 440V.



Crane gantry in engine room, SWL should be marked for all visible.



Bilge alarm test records



General views for Generator side (3 sets)



### Cleaning condition for Generators





Arrangement of E/R




Walkway and arrangement of E/R



Escape route



Escape indicator



Randomly test for oil mist alarm, ok



Hype mist system test above incinerator , ok



15ppm alarm test, result ok



OWS test from tank to tank, result ok



Tank top in engine room was found tidy and cleaning condition.



One fire hose in engine room was found in poor condition, engine staffs plan to replace with new parts.



OWS discharge outlet was sealed during port stay.



Flame fault test for incinerator



Checking working condition of sewage treatment



Test communication between steering room and bridge, result ok



The min level of Hyd. Oil for s/g not marked in place

Emergency steering operation was carried out during inspection.





Function test for engine vent was conducted.



The hand levels were found rusty, advised to maintenance by chipping and scrapping



The latch of hook for boat falls were found clogged, advised to fair up and greased up



Test boat engine and steering system, lighting system, result in ok



Checked inventory in lifeboat



Checked inventory in lifeboat



Functional test for rescue boat engine is ok



Switch limit functional test, result is ok



Life raft/rescue boat davits test is ok



Life raft inspection



CO2 room inspected



Mechanical ventilator in CO2 room operative









Emergency fire pump test









Garbage collect drum with post was observed



	in good
	
Sprinkle test in Paint locker, result in good	Non slip passage on deck was found in order. Safe lines with handrails was found in bosun store.
	
Pipe lines on deck	Drainage non return valves
	
Hatch coaming condition	Hydraulic jack for hatch cover operation



	
<p>Pilot ladder condition in order</p>	<p>Pilot ladder brand with ISO standard</p>
	
<p>Movable parts in Bosun need to secure by lashing materials</p>	<p>Movable parts in Bosun need to secure by lashing materials</p>
	
<p>Bilge valves for dewatering system in forward stores was found rust.</p>	<p>Few Chains blocks in forward stores need to maintain with SWL marking post.</p>



Recreation room



Officer mess room



Chamber temp.



Provision stores, to be replenish at Dalian



Galley floor in good condition



Galley condition



MF/HF DSC test, dropped down to 22V after



Searching light test



using of Battery mode



ECDIS setting inspection

UKC setting inspection



Washing machine, all operative

Hospital inspection



Low pressure alarm test for SCBA

Smoke detect test for fire alarm panel.