



Date: 14th Aug 2023

Item

Checked cargo condition at quayside.



Date: 14th Aug 2023

Item

Checked cargo condition at quayside.



Date: 14th Aug 2023

Item

Shipping mark

Plant Name: PL 1057 Pemas
Client: Tenaga Energy Pemas
Destination: Pemas
POD: Gdansk Seaport, Poland
Package No.: 3-0015-000-4-01-7000000000
Supplier's Package No.: PJ 20170
UCR No.: SIEM0000170000
Gross weight: 2175 kg
Net weight: 1700 kg
Dimension (L x W x H): 224 x 224 x 224 cm
Supplier: JIANGSU HUAPENG TRANSFORMER CO., LTD




	<p>Date: 14th Aug 2023</p> <hr/> <p>Item</p> <hr/> <p>Checked cargo condition at quayside.</p>
	<p>Date: 14th Aug 2023</p> <hr/> <p>Item</p> <hr/> <p>Shock log was in normal condition</p>
	<p>Date: 14th Aug 2023</p> <hr/> <p>Item</p> <hr/> <p>Checked cargo condition at quayside.</p>



Date: 14th Aug 2023

Item

Checked cargo condition at quayside.



Date: 14th Aug 2023

Item

Dunnage and securing condition at truck



Date: 14th Aug 2023

Item

Shock log was in normal condition



Date: 13th Aug 2023

Item

General view of vessel bow



Date: 14th Aug 2023

Item

Lifting beam (SWL90T)



Date: 14th Aug 2023

Item

General view of soft slings



Date: 14th Aug 2023

Item

Soft sling (SWL-20T/10M)

	<p>Date: 14th Aug 2023</p> <hr/> <p>Item</p> <hr/> <p>General view of soft sling</p>
	<p>Date: 14th Aug 2023</p> <hr/> <p>Item</p> <hr/> <p>Soft sling (SWL-20T/4M)</p>
	<p>Date: 14th Aug 2023</p> <hr/> <p>Item</p> <hr/> <p>Shackle (WLL 25mt)</p>



Date: 14th Aug 2023

Item

Container crane (SWL-80T)



Date: 14th Aug 2023

Item

General view of rigging gear assembly



Date: 14th Aug 2023

Item

General view of flat rack arrangement onboard
CAXU5724949 at bay 861322,
DRYU1402666 at bay 861522,
TRIU0809852 at bay 861722,
TRIU0784060 at bay 861922



Date: 14th Aug 2023

Item

Loading operation



Date: 14th Aug 2023

Item

Loading operation



Date: 14th Aug 2023

Item

Loading operation



Date: 14th Aug 2023

Item

Loading operation



Date: 14th Aug 2023

Item

Loading operation



Date: 14th Aug 2023

Item

Transformer was in position



Date: 14th Aug 2023

Item

Loading operation for second transformer



Date: 14th Aug 2023

Item


Loading operation



Date: 14th Aug 2023

Item

Loading operation



Date: 14th Aug 2023

Item

Loading operation



Date: 14th Aug 2023

Item

Loading operation



Date: 14th Aug 2023

Item

Loading operation



Date: 14th Aug 2023

Item

Lashing belt (WLL-5T) =MSL10T



Date: 14th Aug 2023

Item

General view of buckle condition



Date: 14th Aug 2023

Item

Lashing condition



Date: 14th Aug 2023

Item


Lashing condition



Date: 14th Aug 2023

Item

Edge protection applied



Date: 14th Aug 2023

Item

Dunnage with rubber



Date: 14th Aug 2023

Item


Lashing condition



Date: 14th Aug 2023

Item

Lashing condition



Date: 14th Aug 2023

Item

Lashing condition



Date: 14th Aug 2023

Item

Lashing condition



Date: 14th Aug 2023

Item

Lashing condition



Date: 14th Aug 2023

Item

Lashing condition



Date: 14th Aug 2023
Item

Lashing condition



Date: 14th Aug 2023
Item

Lashing condition



Date: 14th Aug 2023
Item

Lashing condition



Date: 14th Aug 2023

Item

Lashing condition



Date: 14th Aug 2023

Item

Lashing condition



Date: 14th Aug 2023

Item

Over view of lashing condition for two transformers